




200W USB-C 6-PORT PD GAN CHARGER




1 Connect the included C5 power cable to the C5 connector on the rear of the charger.




2 Plug the power cable directly to a power outlet.




3 The LED Indicator light will illuminate white when receiving power.



4 The 200W charger can be laid flat horizontally on the supported rubber feet or vertically using the included Desktop Stand.




5 Plug in cables (sold separately) to the charger's USB-C PD ports. We always recommend using certified charging cables. EMARK cables are required to reach wattage above 60W.




6 Connect and charge up to six USB-C devices simultaneously. Total max output: 200W. When connecting devices to all six PD ports, connect your largest device to the PD1 port.


CHARGING



When connected to PD1 or PD2, supported device can charge with a max output of 140W.
Only one device can be connected at a time to either port in order to achieve 140W charging.
USB-C to MagSafe 3 Cable must be used in order to achieve 140W output through PD1 or PD2.



When connected to PD3 or PD4, supported device can charge with a max output of 100W.



When connected to PD5 or PD6, supported device can charge with a max output of 20W.