



front side - voorkant  
- face avant - Vorderseite - lado delantero - przód

solder side - côté soudure - soldeer zijde - Lötseite - lado de la soldadura - strona lutownicza




Watch the polarity!  
Att. la polarité!

◇ C1: 47µF / 16V




◇ SW1 (KRS0612)

**1 Resistor - Weerstand - Résistance - Widerstand - Resistencia - Motstand - Vastus - Resistenze**



front side - voorkant  
- face avant - Vorderseite - lado delantero

◇ R1 ... R7: 270 E (Red, Purple, Brown) - (Rood, Paars, Bruin) - (Rouge, Violet, Brun) - (Rot, Violet, Braun) - (Röd, Lila, Brun) - (Punainen, Purppura, Ruskea) - (Rojo, Morado, Marrón) - (Encarnado, Violeta, Castanho) - (Rosso, Viola, Marrone) - (czerwony, fioletowy, brązowy)




Watch the polarity!  
Att. la polarité!

◇ LD1 ... LD16: white diffused LED (L-5WDN/1)


front side - voorkant  
- face avant - Vorderseite - lado delantero - przód

**2 Cermaic capacitor**



◇ C2: 100nF (104)


**3 IC**



Watch the notch!  
Att. l'entaille!

◇ IC1: VMK199 (programmed PIC16F1503-1/P)

**7 Battery holder**



- Press switch: ON
- 1 x soft light
  - 2 x strong light
  - 3 x strong inside
  - 4 x strong outside
  - 5 x slow fade
  - 6 x quick fade
  - 7 x slow inside to outside fill
  - 8 x explode
  - 9 x implode
  - 10 x flashing LEDs #1
  - 11 x counter clockwise rotation
  - 12 x clockwise rotation
  - 13 x spiral in and out
  - 14 x flashing LEDs #2
- Press long: OFF